
Imperial Railways of North China.

Report for the Year ended 31st December, 1911.

Published for circulation by order of the Directors.



Imperial Railways of North China.

GENERAL REPORT.

The Directors submit the following report of the working of the railway during 1911. The year was one of grave vicissitudes and the operations were carried out under extremely difficult conditions. Early in the month of January, pneumonic plague broke out in Manchuria and rapidly assumed serious proportions. It was responsible for thousands of deaths and in order to prevent, as much as possible, dissemination of the disease over the wide districts served by our line, all transportation of passengers from Mukden and Outside Wall stations was stopped, for a time, and subsequently only recommenced under quarantine regulations. The summer floods caused much damage and in certain parts famine relief had to be organised by the Government. In the closing months of the year, the revolution, which broke out at Wuchang, made great demands on the traffic facilities of this line for speedy transportation of large bodies of troops and military equipment and, in the opinion of those competent to judge, the operations, though of great magnitude, were efficiently and promptly performed. In spite of these difficulties the earnings have been well maintained.

The results of the Year, compared with 1910, are as follows:-

Ear

Ex

Ba

	Year ended 3	st December.
	1910	1911
	\$	\$
nings	10,928,242.31 3,474,187.35	11,668,627.89 3,651,132.53
ance after paying Working Expenses.	\$ 7,454,054.96	8,017,495.36
io of Working Expenses to Earnings	31.7%	31.3%

Mileage—There has been no change in the number of miles of main line open to traffic.

Loans—The Imperial Chinese Railways 5% Gold Loan of 1899 was reduced on 1st August, 1911, by the amount of the Seventh Drawing of £ 57,500. to £ 1,897,500.

The half yearly payments to the South Manchuria Railway in reduction of their Gold Loan have also been duly met.

Exchange—The monthly remittances to London for repayment of Loan Capital and Loan Interest were made at the average rate of 2/61/2 per Tientsin Tael.

Staff-The Directors take this opportunity of thanking the Staff for their co-operation throughout the year.

Li Tsoi Chee, Managing Director Shu Yin Chi, Director

_ 3 -

IMPERIAL RAILWAYS OF NORTH CHINA.

STATEMENT OF ACCOUNTS

FOR THE YEAR ENDED 31st DECEMBER, 1911.

No. 1

Capital Authorised and Created.

DETAILS	Ca	apital Author	rised		Capital Creat	ed			
DETAILS	Stock and Shares	Loans	Total	Stock and Shares		Total	Stock	Balance	
Imperial Chinese Govern- ment and Chinese Share-	\$	\$	\$	\$	\$	S	Shares	Loans	Total
Under Loan Agreement)	21,994,428.57			21,994,428.57	-	21,994,428.57	\$	\$	\$
Jnder Japanese Loan Agreements, South Man-		27,600,000.00	27,600,000.00	-		27,600,000.00	The second		
churia Rly. Loan, 1909, Gold Yen 320,000	_	377,142.86	377,142.86		377,142.86	377,142.86			
\$	21,994,428.57	27,977,142.86	49,971,571.43	21,994,428.57	27,977,142.86				

No. 2 Stock and Share Capital Created Showing Proportion Issued.

	Amount Created	Amount Issued	Amount Unissued
mperial Chinese Government and Chinese Shareholders	\$ 21,994,428.57	\$ 21,994,428.57	\$
s -	21,994,428.57	21,994,428.57	_

No. 3

Capital Raised by Debenture Stock.

		\$
Imperial Chinese 5% Railway Loan, 1899 (original amount of Loan £ 2,300,000).	£ 1,955,000	23,460,000
Disting at 91st December 1910	57 500	690,000
The second off	C 1 807 500	22,770,000
1 1011		1,807,962.10 784,949.62
Of which there was invested in the nongkong & Stanger	00,1,2,00	1,023,012.48
Leaving invested in the Hongkong & Shanghai Bank, London, at 31st December, 1911	£ 85,251. 0.9	1,020,012
South Manchuria Railway Loan, 1909 (original amount of Loan G. Yen 320,000.00). Existing at 31st December, 1911		

Receipts and Expenditure on Capital Account.

No. 4 Receipts and Expenditure on Capital

Dr.	Total	Amount expended in Year	Total to 31st Dec.		Total to 31st Dec. 1910	During Year 1911	Total to 31st Dec. 1911
	1910	1911	1911 S	By Receipts	\$	8	8
To Expenditure Lines open for Traffic Authorised by High Court	47,245,485.01 1,139,123.98		47,245,485.01 1.849,711.38	Shares			21,994,428.57 27,600,000.00
of Chancery	004 000 00	72,475.78	336,475.78	South Manchuria Rly. Loan			877,142.86
\$	48,648,608.99		49 431,672.17 539,899.26				
Balance		\$	49,971,571.43			s	49,971,571.43

No. 5 Details of Expenditure on Capital Account.

						_														1	\$
Land and Earthworks			18															*		-	30,510.51 192,405.54
Rolling Stock								*				*		*		-			-	-	42,538.65
Tongshan Works		*		,	*	*	*			*	*				*	*		*	*		10.323.11
Shanhaikwan Bridge Works New Head Office Buildings																				_	98,472.02
Stations and Yards																					176,869.63
Bridges																				_	111,351.56
Staff Quarters																				_	32,126.41 15.989.97
Miscellaneous				*													*		*	-	10,000.01
																				0	710.587.40
	-																			9	110,001.40

No. 6 Expenditure on Capital Works paid for from Revenue.

tterments.	S
Railway Extension to Mukden City	80,384.98
Expended during Current Year	
	8,983,970.27

General Balance Sheet Dr. Hongkong and Shanghai Bank, London Capital Account, Balance per No. 4 539,899.26 206,937.44 Loan Funds, on Deposit Receipt . £ 50,000.0.0 Loan Funds, on Current Account . 35,251.0.9 1,023,012.48 475,358.79 3,293,107.44 5,477,242.12 Revenue Funds, on Deposit Rect . £75,000.0.0 Revenue Funds, on Current Ac-To meet repayment of Loan Capital Cash with foreign Banks in China 269,827.94 Cash on hand in Head Office Investments Traffic Accounts due to the Railway Other Accounts due to the Railway Accounts due by other Railways 9,992,545.05

No. 9

Wm. Henderson, C.A., Chief Accountant.

ABSTRACTS.

A. Maintenance of Way, Works and Stations.

Year of 31st Decer	nding	81	st December, 1911
\$ \$	\$ 174,403.29	Salaries, Office Expenses and General Superintendence	191,683.94
		Maintenance and Renewal of Permanent Way:-	0.074.07
298,007.03 223,306.98	521,814.01	. Wages	9,974.67 613,944.07
		Repairs of Bridges.	
12,997.21 Cr.5,433.93	7,563.28	. Wages	13,432.65 20,197.26 33,629.91
\$	72,645.74	Repairs of Stations and Buildings.	90,763.63

B. & C. Locomotive Power and Rolling Stock Repairs.

Year e 31st Decen	ending ober, 1910											Year end	
\$	\$										-		
	130,542.21		Salar	ies, Off	fice Exper	nses and Gener	al Superin	ntender	nce				157,039.29
					Run	ning Expens	es						
150,387.43 447,862.20 48,886.45 61,366.77	708,502.85		Wat	ter .		er Stores			nes			153,001.77 438,469.72 46,070.46 66,342.09	703,884.0
		Mainte	nance	and	Renewa	l of Locome	otives a	and N	lachin	ery:	_		100,004.0
293,853.05	444,609.61					. Wages . Materials						811,673.83 99,723.04	444.000
				Repa	airs and	Renewals	of Car	s:				00,120,04	411,396.
61,855.36 62,480.67	124,336.03					aching Vehicle . Wages . Materials						81,297.64	
61,743,93					G	oods Vehicles . Wages .						59,124.33	140,421
03,466.68	165,210.61		,			Materials					,	71,136.66 91,868.81	
	1,625,050.00				Cleaning	g Carriages and	d Oiling						100,00
\$	12,753.69				Steam	Ferry at New	chwang						1,617,75 11,33
													1,629,09

Year ending Sist December, 1910			31st Prepar
\$ \$2,719.50 \$15,544.40 \$6,550.66 \$4,545.66 \$4,5661.40	General Superintendence Wages of Station Staff Wages of Train Staff Lighting and Small Stores Wagon Covers, Ropes, etc. Station Fittings and Furniture		" 35 35 35 35 35 35 35 35 35 35 35 35 35

E. General Charges.

- 1	_					31st December,
5	5					
274.834.46			-			General Superintendence .
66,519.92		_		-		Accountant's Department
91.352.71						Stores Department . 68.106.96
91,352.71 45,497.97	1					Medical Department . 77,064.89
10,005.70						Rents of Buildings and Lands . 100,957.40
106.371.81	1.					Police
117,156.81						Telegraph Department . 111,765.52
68.708.51	1-					Stationery and Printing . 151,989.01
2,659,57						Compensation - 58157 79
54,627,89						Sundries . 3.874.42
37,735.35						35,639.47
81,939.41						
	5,795.94		-	-	-	Interest, &c

EARNINGS.

8 8 8 5,141,402.46 5,394,226.01 29,215.33 244,098.76 119,299.75		Passengers Goods Military Traffic Miscellaneous Receipts		Year ending 31st December, 1911 \$ 4,336,997.08 5,931,056.62 53,092.51 399,094.18
10.928,242.31		Chinese Government Traffic		948,387.50

AUDITOR'S CERTIFICATE.

The accounts for the year ended 31st December, 1911, as stated, contain, in my opinion, a full and true statement of the financial condition of the Railway, and the revenue has, in my judgment, been charged with all expenses which ought to be paid thereout. The interest and redemption of the Loan during the year have been fully met.

Tientsin, 11th March, 1912.

A. F. Algie,

ENGINEER-IN-CHIEF'S CERTIFICATE.

I hereby certify that the Permanent Way, Bridges, Stations and other Buildings have been maintained in good order during the year 1911.

Tientsin, 9th March, 1912.

D. Poyntz Ricketts,

Engineer-in-Chief.

LOCOMOTIVE SUPERINTENDENT'S CERTIFICATE.

I hereby certify that Plant, Engines, Machinery and Tools have been maintained in good repair. After the outbreak of the revolution the coaches and cars suffered considerable damage in the for.

After conveyance of Imperial troops. A large number of cars on foreign lines are still unaccounted

Tongshan, 31st December, 1911.

F. A. Jamieson,

Locomotive Superintendent.

REPORT ON PERMANENT WAY DEPARTMENT.

Miles of Main Line Track Miles of Sidings, permanent temporary Increase of Main Line Increase of Sidings, permanent temporary 198,067 New Sleepers put in for Maintenance. 147.644 7.780 Total 155.424 2.960 5.566 Total 7.163 198,067 New Sleepers put in for Maintenance. 14 Old Section 60 lb. Rails changed.	
16 New Section 60 lb. Rails changed. 5—85 lb. Rails changed. 1 Japanese Rail changed. 0.97 Mile of Old Section 60 lb. rails in sidings have been replaced by New Section 60 lb. 14,101 fangs of Ballast for Maintenance. 9,937 fangs of Ballast for New Work. 3,059 Floor Ties renewed.	

New Works Completed:-

Additional Ramp to Tientsin East footbridge. Footbridge of two 69 feet spans with 5 ramps at Tientsin Central. Bridge No. 20a. 4 spans 10 feet reinforced concrete slab top. Bridge No. 34a. 4 spans 10 feet reinforced concrete slab top. Bridge No. 34b. 4 spans 10 feet reinforced concrete slab top. Bridge No. 55. raised 3'6". Bridge No. 56. 10 new 30 feet spans added, and raised 6'0". Bridge No. 57. raised 6'0". Bridge No. 65. extended 2-20 feet spans. Bridge No. 66. extended 3-20 feet spans. 13,835 fangs of Rubble used for protective work:— (a) For maintenance.
(b) For new work 48,063 fangs of Earthwork executed: 7,141 fangs
(a) For new work

Platforms Extended:-

Paotungssu, 100 feet run masonry wall. Lienshan, 600 feet for Hulutao Junction.

New Buildings Erected:-

Buildings Erected:—	
Tientsin City Station.	
Two open steel waiting sheds with galvanized covering .	8,475 square feet
Tongshan.	-01
Weighbridge	784 do
Store for electric fittings	1,092 do
Store lean-to on engine shed	438 do
Additional room, Traffic Inspector's quarters	289 do
Two open wooden waiting sheds with galvanized covering .	6,869 do
Hsukochuang (near). Two platelayer's houses	040 3
Two platelayer's houses	840 do
Hanku. Reiden watchman's but	1-0 1
Bridge watchman's hut	156 do
	040 3
Police quarters	640 do
Additional room engineer's quartors	1-0
Additional room engineer's quarters	470 do
	0-0-
Police quarters	2,535 do
Waiting room	2,485 do
Administration Offices	
Administration Offices	32,478 do
Electric power house and quarters	2,587 do
Stable and quarters for Head Office Staff.	3,861 do
I wo signal cabins	R9A A.
Addition to police quarters	665 do
Lisinu,	
Platelayer's cabin	404 do
Electric power house	1,757 do
	1,297 do
Plague huts	4,735 do
7	111 1 1 1
The state of the s	4 000
ANTIGO TITLES WALLED	
	410 do
Shahouso.	168 do
Station Staff quarters	2 -00
Chinchow.	2,796 do
Weighbridge house	
Shuangyangtien.	168 do
Police quarters	
Police quarters	450 do
Police quarters	
Police quarters	450 do
Loco quartors	490 do
Loco quarters Plague huts	9.750
Plague huts Lichiawopu.	2,750 do
Weight in	2,880 do
Weighbridge house	
TISHIHIHIU.	168 do
Weighbridge house	
Police quarters	168 do
Traffic quarters	9.059
Latrine	7,560 do
onununo,	001
EHOTIVOOR'S AP	
LIQUIC OF THE STATE OF THE STAT	
Oferk's quarters	uu
	1,094 do
	40

REPORT ON PERMANENT WAY DEPARTMENT.

Miles of Main Line Track
Increase of Main Line
198,067 New Sleepers put in for Maintenance. 14 Old Section 60 lb. Rails changed. 16 New Section 60 lb. Rails changed. 5—85 lb. Rails changed.
1 Japanese Rail changed. 0.97 Mile of Old Section 60 lb. rails in sidings have been replaced by New Section 60 lb. 0.35 mile of 45 lb. rails in sidings have been replaced by Old Section 60 lb. 14,101 fangs of Ballast for Maintenance. 9,937 fangs of Ballast for New Work. 3,059 Floor Ties renewed.

New Works Completed:-

Additional Ramp to Tientsin East footbridge. Footbridge of two 69 feet spans with 5 ramps at Tientsin Centr Bridge No. 20a. 4 spans 10 feet reinforced concrete slab top. Bridge No. 34a. 4 spans 10 feet reinforced concrete slab top. Bridge No. 34b. 4 spans 10 feet reinforced concrete slab top. Bridge No. 55. raised 3'6". Bridge No. 56. 10 new 30 feet spans added, and raised 6'0". Bridge No. 57. raised 6'0". Bridge No. 65. extended 2-20 feet spans.	al.	
Bridge No. 66. extended 3-20 feet spans.		
13,835 fangs of Rubble used for protective work:-		
(a) For maintenance	6,694	fangs
(b) For new work	7,141	tangs
(a) For now work	10 100	
(a) For new work	40,139	langs
(b) For repairs	7.924	fangs

Platforms Extended:-

Paotungssu, 100 feet run masonry wall. Lienshan, 600 feet for Hulutao Junction.

New Buildings Erected:-

New Buildings Erected.—		
Tientsin City Station.	0 1==	wann book
Two open steel waiting sheds with galvanized covering .	8,410 80	quare feet
Tongshan.	784	do
Weighbridge	1,092	do
Store lean-to on engine shed	438	do
Additional room, Traffic Inspector's quarters	289	do
Two open wooden waiting sheds with galvanized covering .	6,869	do
Hsukochuang (near).		
Two platelayer's houses	840	do
Hanku.		
Bridge watchman's hut	156	do
Pelian granton	010	1
Police quarters	640	do
	470	da
	410	do
Transata tangent transatt.	2,535	do
		do
by where were were were the property of men word with	2,200	uo
	32,478	do
		do
ce Staff	3,861	do
lagrolesees no sales edus	624	do
The state of the s		do
	000	uo
terly mest edely dens a sold	404	do
		40
BILLY TROUBLE BUILD BUIL	1.757	do
		do
to assume to assume and assume	,,_,,	40
	4,735	do
M William Double Roll will be a find a find of the fin		do
	1,683	do
. STRIC SOUT B MARO TO SWOT	1,638	do
ger	410	do
	168	
TOT HOOG SEN MOU STIT TOTAL TO THE TOTAL T	100	do
	2,796	do
AN METT TO STOR TOTAL ONE TOTAL	2,100	do
	168	1-
The same of the same and the same of the s	100	do
	450	1.
The past to war a transfer and	490	do
	450	,
	450	do
Plague huts	9.750	
	2,750	do
Lichiawopu.	2,880	do
Weighbridge house	100	
Hsinminfu.	168	do
Weighbridge house		
Police quarters Traffic quarters	168	do
Traffic quarters Latrine	2,052	do
Chuliuho. Chuliuho.	7,560	do
Chuliuho.	100	do
Engineer's office Clerk's quarters		
Clerk's quarters	737	do
	1,094	do

New Buildings Erected (continued).

Tawa.										
Weighbridge house									130	0.000
Police quarters									450	square feet.
Huchiawopu.									100	do
Police quarters									450	
Suichunghsien.									49()	do
Weighbridge house									100	
Chinehow							•		168	do
Locomotive School									700	
Hsinlungtien.									729	do
Station latrine	antona			*					263	do
Additional Locomotive staff qua	arters	*							1,678	
Mukden City.										do
Temporary station building .									2,124	
Platelayer's cabin				-				100	110	do
										do
	Total		-						118,509	square feet
		-							,,,,,,	square test

Turntable put in.

Lienshan. 53 feet Turntable put in for Hulutao Junction.

Signals Erected.

Tongshan. Two shunting signals in Locomotive Yard.

Tientsin City Station. Main Line and connecting rods all interlocked and signalling East cabin 24 levers (4 spare), West 30 levers (8 spare).

Heavy Works Executed: -

Tientsin City Station. New Administration Offices.

Plague camps at Shanhaikwan, Kaopantzu and Yingkow.

New sidings, turntable, and platform at Lienshan for the Junction to Hulutao harbour.

Bridge No. 248. Training spurs put in to check the erosion of the west bank.

50 ton weighbridge put in at Shanhaikwan, Chinchow, Kaopantzu, Yingkow, and Hsinminfu.

30 ton weighbridge transferred to Suichunghsien, Lichiawopu, and Tawa.

The Hsinminfu station dam has been raised and widened, a clay blanket has been laid for 10,500 feet and 65 spurs have been made with protected ends. Additional protection works were constructed on the main line West of Hsinminfu station, near bridges 53 and 54. The Main Line bank was raised from No. 57 Bridge up to the Liao River bridge, and relaid with new section 60 lb. rails and ballasted. Chuliuho station platforms raised 6 feet, and Hsinminfu 3 feet.

10 spans have been added to No. 56 bridge, and Nos. 20a, 34a, and 34b bridges have been built, each 4 spans of 10 feet. Additional quarters have been built for staff.

Formation raised 3 feet from chainage 4,175 to 4,290, 11,500 feet.

Bridge No. 65 extended 2 spans of 20 feet, and bridge No. 66 extended 3 spans of 20 feet Main line extended to temporary station outside Mukden City wall, and loop from temporary station to South Manchurian Railway boundary, total length added to main line 2.96 miles.

Foreshore Protection:

Tongku bund reformed and pitched, 680 feet. 36 fangs rubble used at Yingkow.

Painting Executed for Maintenance:

Bridges (East of Tongku) Nos. 21, 48, 50 to 60 inclusive, 63, 64, 65, 69, 71, 73 to 87 inclusive,

113 and 5. 71/2' culverts. Bridges (West of Tongku) Nos. 4, 24, 34 to 41 inclusive and Tungchou Branch 1 to 9 inclusive.

Peitaiho. Stationmaster's house.

Anshan. Water tank.

Changli. Two water tanks.

Yangminho. One water tank.

Tongku. Part of Engineer's quarters.

Tientsin. Locomotive and Traffic quarters.

Fengtai. Waiting room.

Signals, station name posts, point rodding, sign posts, etc.

The Railway Hotel Shanhaikwan, quarters and station building, Shanhaikwan, Suichunghsien, Ningyuanchou, Koupangtzu, Chuliuho and Yingkow. Overbridges at Shanhaikwan, Chinchou and Koupangtzu. Ferry and pontoons at Yingkow. Lamp posts, whistle boards, milestones, cabins and bridge numbers, etc.

Bridges Nos. 135, 136 and up to and inclusive 149, 152 to 154, 156 and 157 and 161, have

been painted.

Bridges Nos. 209 to 223, 228 to 253, and 276 all inclusive have been painted.

Water Supply Works:-

Changli. Direct connection made from Yangminho pump, and pipe tapped at Changli, to enable water to be flushed through.

Tientsin. Water column at East end, replaced by a new one, 860 feet pipe laid to supply

water to new waiting rooms.

Tientsin City Station. City water laid on to New Administration Offices and to power house. Yaoyangho. Two tanks increased 4 feet in height.

Works in Progress:-

Bridge No. 106 (East of Tongku) Training banks.

Tongshan. Paint shop.

Drying shed.

Changkueichuang: Station building.

Tientsin. Engine shed. Platform paving.

Waiting room.

Tientsin City Station. Junction signalling (almost finished). Rice siding. Bridge No. 2. Reconstruction.

Chienmen. Metalling goods yard and road.

Octroi shed. Post office.

Bridge No. 58. 17 spans of 30 feet.

Mukden. (Fengtien). Station yard earthwork filling.

Rainfall and Floods:

Rainfall Lanchou. 37.49 inches, Tongku 39.63 inches, Fengtai 23.10 inches.

No damage was done by floods due to rainfall in the Inside Wall District, but considerable damage was done to the embankment between Tongku and Peitang by a very high tide and gale on August 30th.

Shanhaikwan-Shahouso Section. No serious damage was done by floods with the exception of No. 175 bridge, the bank of which was badly scoured out on the North West side.

This river requires training.

Shahouso-Chinchou Section. No serious damage done by floods, but Bridges Nos. 239, 264 (Niuerho), and 271 (Hsiaolingho) all require more or less heavy training works to stop the erosion of the banks, especially No. 264, which suffered badly.

Chinchow-Kaoshantzu Section. On July 12th the North East training bank of No. 279 bridge was carried away, and the bank slightly damaged behind the East pier of the bridge. The South side wing walls of No. 296 bridge were carried away. A slight washout

occurred at Shuanyangtien station.

Koupangtzu-Yingkow Section. On August 12th a heavy storm prevailed, during which 14 inches of rain fell in 40 hours. The overflow of the Liao flooded the plain, and the Railway from Huchiawopu to Tienchuangtai was exposed to floods for the first time since it has been built. The natives attempted to cut the bank near Huchiawopu but owing to the water being nearly level on both sides, the damage was easily repaired. With the exception of gulching and fretting of slopes, no other damage was done to the Railway.

Rainfall and Floods (continued).

Kaoshantzu-Chuliuho Section. In April owing to the Spring floods, the station dam at Hsinminfu was breached, but traffic was not suspended. In June a rise of 2'6" occurred Hsinminfu was breached, but traine matrixe dam, North of Hsinminfu and damaged but in the Liu river, which breached the native dam, North of Hsinminfu and damaged but in the Liu river, which of eached the Mally 9th the Liu water rose to 205,00, the Railway did not break the Railway dam. On July 9th the Liu water rose to 205,00, the Railway did not break the Railway dam. On the Hsimminfu station. This flood was very troublesome as the river channel shifted into the breach, much silt was deposited in Hsinminfu yard, and the tracks disarranged. The river was dammed, and headed off in another direction, and the embankment and tracks were then repaired. Traffic was stopped from 10th to 13th. On July 20th the Liao river rose to 195.30 and flooded the Chuliuho store yard and engineer's offices, and this state of affairs continued more or less to the middle of August, when a heavy rain storm aggravated the situation, and caused a general flood in Liao. The scour through No. 58 bridge was strong, and eventually the training banks were undermined and lost, thus allowing the main line to be breached, behind the West abutment, for 150 feet. The maximum depth of the scour hole was 40 feet from the surface of the water, the only thing that could be done was to fill up the hole with stone and ballast. This was done as rapidly as it could be supplied by all the quarries on the Railway, and traffic was resumed on August 29th. The abutment of the bridge No. 58 disappeared and one girder was lost. A new bridge consisting of seventeen 30 feet spans is being built to replace the old one, three spans of 20 feet, which will be filled up. During this flood, the Railway was threatened by water topping the formation level at Tahushan, and at bridges Nos. 40 and 41 West of Peichipu,

The Rainfall registered on different sections as below:

Shanhaikwan 365/8", Ningyuanchou 327/8", Koupangtzu 32", Yingkow 371/4" and Chuliuho 28". Mukden Rainfall totalled 37 inches, including 12 inches in July and 13 inches in August.

The Liaoho reached maximum height on 23rd July and overflowed its banks topping bank to Eastward, for about 2 miles, and breaching it in several places. The largest breach was 100 feet long × 16 feet in depth. Train service was suspended till the morning of the 24th August when it was resumed, passengers being transhipped at the breach. Through traffic was resumed again on the evening of the 27th July.

On 12th and 13th August 12" rain fell in 36 hours, caused another flood, practically the whole of line between Liaoho and Mukden being effected. The track was awash in many places and washouts were frequent. One (at Bridge No. 62) extending to a length of 300 feet and 20 others of 30 feet and over, and 70 to 80 of from 5 to 10 feet. In consequence of this, the train service was suspended from 14th to 27th August.

Shanhaikwan Bridge Works.

The tonnage of work turned out was as follows:-

Girders:

18 spans 100 feet clear													Tons	655.	9.	1.	6.
11 spans 12 feet clear														18.	3.	3.	11.
11 spans 10 feet clear															7.		
3 spans 21'6" Differdange .															3.		
59 spans 20 feet Differdange														195			
30 spans 10 feet Differdange									•						15.		
3 spans 13 feet 2 inches															15.		
1 26 feet girder for Tientsin	H	ea	d	Ó	fic	e	Bu	iile	liı	10.8	,				16.	0.	21.
										0		_					_
													Tono	950	13	1	7.

Special Work, Tanks etc:— 2. 15 feet diameter × 10 feet Water Tanks 1. 13 feet diameter × 10 feet Water Tank 1. Single 41 feet clear steel Overbridge with 2.1 in 6 ramps for Kinhan Railway 1. Double 41 feet clear steel Overbridge with 3.1 in 6 ramps for Kinhan Railway 2. Steel waiting sheds, each 110 feet 3³/4 inches × 38 feet 6 inches, Tientsin City Station 1. Double 69 feet clear steel Overbridge for Tientsin City Station 4. 4 feet × 4 feet × 8 feet plate iron Oil Tanks for Koupantzu Shop 3. Plate iron Oil tanks 4 feet × 4 feet × 4 feet for Koupantzu Shop 1. Set Steel Roof Truss 44 feet 4 inches × 13 feet high for Lanchou	Tons	1.	7. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	2. 3. 1 2. 2 3. 3 3. 3	4. 26. 26. 14. 17.
	Tons	186.	6.	4.	12.
Miscellaneous:					
Ironwork to the extent of	Tons	73.	4.	3.	0.
TOTAL TONNAGE of Ironwork done	Tons	1210.	5.	0.	19.
Foundry:					
The Foundry has been fully employed upon Railway chairs, Signal gears, Columns, Castings for washout pumps, Points and Crossings, Water cranes, Turntables and Miscellaneous Castings for Maintenance and Construction, to the extent of	Tons	181.	2.	2	. 0.

- 1 Pipe, screwing and cutting machine.
- 1 Drilling machine.
- 1 New Smith Forge with pipe for Points and Crossing Shop. 1 Old Cold Sawing machine supplied from Tongshan Works.
- 1 Old 38" Blast Fan supplied from Tongshan Works.
- 2 sets New wall Drilling machines.
- 1 New 24" Gap Shearing and Punching machine.

GENERAL REPORT OF WORK CARRIED OUT BY LOCOMOTIVE AND CARRIAGE WORKS.

Locomotives.

General overnaul		40.00					
Repaired at Koupangtzu				-			44.
Repaired at Koupangtzu	5	Rin				*	15.
Locomotives fitted with Westinghouse brake	0	0		*			1.
Locomotives fitted with Westinghouse brake Locomotives fitted with the Westinghouse train heating gear New Boilers constructed for renewals							1
Nocomouves nited with the westinghouse train heating gear						4	8
New Boilers constructed for renewals						1	e.
THE WALLEY PROPERTY OF THE PARTY OF THE PART							
New back plates put in	•						11.
Now cots of tubes put in							7.
New sets of tubes put in							23.
Doners withingawn from service							
New Deliders Dulle							-
renders repaired at rongshan works	4						~ ~
Tenders repaired at Konpangtzu							10
		23111	-		*	1	14.

Steamers.

Ferry boat, s.s. "Liaotung" engines and boilers overhauled.

Coach and Car Repairs.

	No. of	Cars sent in fe	or repairs
	Freight	Passenger	Brake Vans
At Tongshan Works .	1802	206	21
At Koupangtzu Works.	579	46	34
Total	2381	252	55

Note:-At the Running Sheds 11,135 minor repairs were effected to Cars, and 25,332 axle boxes were repacked.

Rolling Stock Completed.

				,			,							50
										*	*	*	1	00
		1	,	*	*		*	*	,	*		*		20
	- 4													100
- 10	-													24
14	- 4	7.6												-
					*	*		,	*	+	,	1	*	1
1	a	à	1	1 1	1	*	,			*				2
4	-0-	-0	1)y)	un	de	l'S	1	8"	3	X	24	133	
		-	-											4
				-						*		*	*	- 0
		-		,	1		*		. *	*	,	*		2
1.	-	10		-	١.		- 1							
	10	16	1	1	10	n	81	n	UC	ti	0	n.		
	4	4-6	4-6-0	4-6-0	4-6-0 Cy	4-6-0 Cylin	4-6-0 Cylinde	4-6-0 Cylinders	4-6-0 Cylinders 1	4-6-0 Cylinders 18"	4-6-0 Cylinders 18"	4-6-0 Cylinders 18" ×	4-6-0 Cylinders 18" × 24	4-6-0 Cylinders 18" × 24" Under Construction.

First Class Sleepers .					,		,	,									6
Decond Class Dieepers		4	6			1	4										- 1
PHSU Class Duneu.	*	16			-	2	2										- 4
Drawing Room Cars											*		*	*	1	*	1
20 Ton Covered Good	18			*		•	,		*	*		*	*	*		*	- 5
First Class Corridor C	lar	Cr.			*		,			*			*	,	*		50
First Class Corridor C	all	0			*		*				*		*				1

Improvement to Rolling Stock.

20 Ton Low Sided converted to 24 ton High Sided	
20 Ton High Sided converted to 24 ton High Sided	200
24 Ton Low Sided converted to 24 ton High Sided	31
24 Ton Low Sided converted to 24 ton High Sided Wagons fitted with coupler locking pin lifting pin lifting	5(
THE COLD MOVE THE COMPLET TOCKING DITT THING WAST	200
77 to 2100 1100 to 000 17 1011 A 661 D 6611111 1 11110 %	
Coach frames fitted with new ends, end platforms enclosed, and vestibules fitted	4
Number of Coaches fitted with piping for steam heating Second Class Coaches fitted with improved seating accommodation Second Class Coach fitted with Electric Light	11
CONTRACTOR CONTRACTOR CONTRACTOR AND	
Coaches fitted with improved buffers. Telegraph car 92 overhauled and converted to	
Telegraph car 92 overhauled and converted to private car.	5

Rolling Stock Withdrawn From Service.

No. 8 Brake Van condemned.

Rolling Stock Completed for other Railways.

Kalgan Railway. Composite
Third Class Baggage, Brake, and Mail
Third Class Baggage and Brake Vans

Ichang Railway. Ping Chao Railway.	Four wheel Brake Van
New	Construction now in Progress for other Railwa
Kirin Railway.	
	17" Cylinder Mogul Locomotive 2-6-0 type, 17" × 24" Drivers 4' 6"
	Old Rolling Stock Disposed of.
	15 Ton Low Sided Cars
	Locomotives
	Varnishing and Painting.
	Locomotives
	Tenders
	Foundry.
T	
B	rass Castings
	Average Number of Employees.
K	ongshan Works
	Total 3,998

Rolling Stock Equipment at 31st December 1911.

		No. of Vehicles	Tonnage.
Freight St	ock. n Capacity:— Powder Vans		
10 To	n Capacity:—		
	Coal Cars	271	60
	Water Tanks	7	2710
	Pig Cars	7	70
	n Capacity:— Coal Cars		
	Coal Cars	471	5652
15 To	Ballast Cars	29	10-
	n Capacity:—	20	435
	Flat Cars	74	1480
	Ballast Cars	258	5160
	High Sided		16480
	Pony		860
	n Capacity:	58	1160
The state of the s	Flat Cars	1	24
	Ballast	16	384
]	High Sided	134	3216
	n Capacity:—		
	Ballast	38	1140
	High Sided	411	12330
	Water Tanks	100	4980
(Oil Tanks	49	1470
,	l'imber	2	60
Passenger			
I	mperial	3	12
	State	3	12
	Private	14	44
	Directors	1	4
9	st Class	24	96
1	Brd Class	38 100	152
(composites	17	68
(Ordinary Buffet	7	28
1	Altenen	1	4
	st Class Buffet	2	8
. 1	and Class Buffet	2	8
Train de	st Class Sleepers	2	8
Luxe 1	nd Class Sleepers	2	8
14	nd Class Saloon	2	8
	reading and Lighting	1	10
11	JUNIOUS DING LANGE	5	20
- who val	5.		20
4	Wheel	50	100
Miscolland	Wheel	15	64
			04
	Vrecking Cars	9	

Passenger Class:-		E	ngines.		
Freight:-	4-4-0	Cylinder	17" × 24" 19" × 24" 18" × 24"	4 3 13	20
Shunters:—	2-6-0	Cylinder Cylinder Cylinder	17" × 24" 19" × 24" 16" × 24"	44 14 27	85
	0-0-0	Cylinder	14" × 24" 16" × 24" 17" × 24"	13 4 2	19
		Tot	al Engines		127

Tenders.

6 Wheel	4	Wheel												3
o wheel bogie		1111111	* * 1		100									00
Total Tenders 114	0	vv neer	Bogie	е.										86
						T	ot	al	T	en	de	rs	-	114

Comparative Table of Rolling Stock.

	1910	1911
Passenger Cars and Brake Vans	287	294
No. of Axles	1036	1068
Freight Cars of all Classes	2814	2868
Tonnage Capacity	56198	57813
Locomotives of all Classes	127	124
Weight in Tons	5745	5667

New Machinery Erected.

Locomotive and	Car Works:— Steam driven log frame saw, for logs up to 36" × 30" New Palening machine to plane 30" × 6" 1.
	Panel planing indenine to plane by X 0
	"Bellis & Morcom" Steam engine direct coupled to Crompton generator. New Vertical boiler, 12'0" × 4'9" diameter for Koupangtzu Shops . 1.

New Buildings and Repairs.

Paint Shop extension of 180 feet in progress.
Timber drying shed 100 feet × 40 feet being put up in Car Works.
Extra rooms added to Locomotive Accountant, Machine Shop, and Erecting Shop Foremens' Locomotive Works Boiler Shop and hydraulic power house fitted with Electric light.
Shops generally white washed and kept in repair.
Offices colour washed.
Scrap furnace added to Locomotive Works Smith Shop.

Miscellaneous Outside Orders.

Vertical boiler 8'9" × 3'6" constructed for Tungpu Railway.
Various Castings for Cement Works, Lanchow Mining Company and other Railways.

TRAFFIC DEPARTMENT.

Train miles run for Revenue	2,057,276 74,234
	2,131,510
Number of Passengers carried	2,974,863 3,189,410
Passenger Mileage	217,785,085 294,633,589
Total "Passenger Ton" Mileage	512,418,674
Average number of men employed by Traffic Department including Military Police about 1560	2,676

TELEGRAPH DEPARTMENT.

Length of Wires.

Tungchow and Tungchow Junction Chienmen and Yingkow Wires (Double Wires). Koupangtzu and Fengtien (Double Wires) Hsinminfu and Fengtien (Single Wire) Tientsin City and Hsiku Tientsin Central and Tientsin East (Six Wires) Tientsin and Tongku (Telephone Wire) Fengtai and Lookouchiao	1043.50 214.50 37.37 4.00 16.00
Electric Staff Wires.	
Chienmen and Fengtien and Yingkow	. Miles 521.75
Number of Messages sent, Service Number of Messages sent, Outside	
	Total 223,290
Average Number of Employees. Number of Telegraph Stations. Number of Recorders in use. Number of Electric Staff Stations. Number of Electric Staff and Tablet Apparatus.	· 77 118

During the year, Telephones have been installed in many of the Principal Stations between Signal Cabins.

Note re: Annual Report for the PMR for the Year ended December 1911

The typed note which follows was found inserted within this copy of the report which had originally belonged to the railway's Chief Engineer C. W. Kinder (金达) who had retired in 1909. Although not signed, Kinder is almost certainly the author of this typed note.

The PMR was formerly known as Imperial Railways of North China prior to the revolution and the overthrow of the Qing government. A large batch of Kinder's personal papers and photographs has survived and is retained by his descendants. These were catalogued by the undersigned and may be viewed as part of the P. A. Crush Chinese Railway Collection. However, 16 boxes of additional less valuable documents consisting of correspondence record books with carbon copies of letters and railway material requisitions etc. were deposited, almost certainly by Kinder's son, at the Manchester Rylands Library sometime during the 1950s. Among these were a few printed official Peking-Mukden Railway Annual Reports covering the years 1909 -1915.

Some copies of annual reports (for the period 1920's-1930's) for the PMR/PNR could also be seen (in 2000) within the Jardines Mattheson & the British & Chinese Corporation (BCC) archives which were retained in 100-plus boxes at the University of Cambridge Library. At this time discussions were in progress on to whether to relocate the BCCC part of this holding to the HSBC archives. The eventual outcome of these discussions and the current location of the BCC records is unknown by the undersigned.

P. A. Crush

(柯睿思)

24.09.2024

Memorandum on steel fireboxes.

My experience in China of the life of steel fire boxes has been on an average of 5 years.

After about 2 to 3 years in service its necessary in general to have large repairs done to them as follows: New half sides, fire box, tube plate, stays renewed, a new set of tubes, & probably a new back plate to fire box owing to the following defects that occur. Plate cracking from stay holes in sides, tube plate, & on occasion, in back plate flanges. Cracking in tube & back plate from rivet holes, plate growing in water ways in line with foundation ring, plate. Pitting between stays & in the roots of flanges of tube & back plates in water ways. Fire box stays frequently breaking in all 4 top corners & top rows of back & tube plate.

After fire box has been repaired as stated above, put in service for another term of from about 2 to 3 years its generally necessary to renew fire box on account of pitting of plate in water ways. & the washing away of crown stays.